Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

Appendix F - Site Audit Summary

May 2022

Items	Date	Status*	Follow up Action		
Water Quality					
Stagnant muddy water was observed.	26 May 2022	#	Follow-up on the next reporting period.		
Ecology					
Noise					
Landscape and Visual					
Air Quality					
Waste / Chemical Management					
Drip tray should be provided to prevent leaked oil from entering drainage system during handling of chemical.	12 May 2022	~	Item was rectified on 19 May 2022.		
Impact on Cultural Heritage					
Permits / Licenses					

- ✓ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit
- * Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit
- # Follow up action will be reported in next reporting month
- * Non-compliance of mitigation measure
- Non-compliance but improved by the contractor

MA20003/App F CINOTECH

Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

Appendix F - Site Audit Summary

June 2022

Items	Date	Status*	Follow up Action		
Water Quality					
Stagnant muddy water was observed.	26 May 2022	~	Item was rectified on 02 June 2022.		
Noise					
Landscape and Visual					
Air Quality					
Waste / Chemical Management					
Oil stain was observed near generator. Contractor is suggested to prepare an emergency spill kit as to clean up spills of oil /chemical. Oil /Chemical was stored at different container. Designated area for chemical storage should be provided for proper storage of chemical /oil. Chemical waste producer license should be displayed	30 June 2022	#	Follow monthup on the next reporting		
properly					
Impact on Cultural Heritage					
-					
Permits / Licenses					

- ✓ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit
- * Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit
- # Follow up action will be reported in next reporting month
- * Non-compliance of mitigation measure
- Non-compliance but rectified by the contractor

MA20003/App F CINOTECH

Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

Appendix F - Site Audit Summary

July 2022

Items	Date	Status*	Follow up Action			
Water Quality						
Noise						
Landscape and Visual						
Air Quality						
Waste / Chemical Management						
Oil stain was observed near generator. Contractor is suggested to prepare an emergency spill kit as to clean up spills of oil /chemical.	30 June 2022	~	Item was rectified on 07 July 2022.			
Oil /Chemical was stored at different container. Designated area for chemical storage should be provided for proper storage of chemical /oil.		~	Item was rectified on 07 July 2022			
Chemical waste producer license should be displayed properly		~	Item was rectified on 07 July 2022			
Drip tray should be provided to prevent leaked oil from entering drainage system.	21 July 2022	~	Item was rectified on 28 July 2022.			
Impact on Cultural Heritage						
Permits / Licenses						

- ✓ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit
- * Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit
- # Follow up action will be reported in next reporting month
- * Non-compliance of mitigation measure
- Non-compliance but rectified by the contractor

MA20003/App F CINOTECH