Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Weekly Site Inspection Record Summary Inspection Information

Checklist Reference Number	250807
Date	07 August 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
250807-EP458-R1	Stagnant water was observed at Portion SB.	B09
250807-EP458-R2	Stagnant water was observed at Portion TY	B09
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• No environmental deficiency was identified in previous session (Ref No.: 250731).	

	Name	Signature	Date
Recorded by	William Yeung	K	07 Aug 2025
Checked by	Karina Chan	Zalle	11 Aug 2025

1 CINOTECH MA20003 $2508_audit_T2_CKL$

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	250815
Date	15 August 2025 (Friday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	 G. Permits/Licences No environmental deficiency was identified during site inspection. 	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:250807), all the items have been rectified	

	Name	Signature	Date
Recorded by	William Yeung	B	15 Aug 2025
Checked by	Karina Chan	Zalle	18 Aug 2025

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	250821
Date	21 August 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality No environmental deficiency was identified during site inspection.	
	 C. Air Quality No environmental deficiency was identified during site inspection. 	
	 D. Construction Noise Impact No environmental deficiency was identified during site inspection. 	
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	 G. Permits/Licences No environmental deficiency was identified during site inspection. 	
	 H. Marine Ecology No environmental deficiency was identified during site inspection. 	
	 I. Others No environmental deficiency was identified in previous session (Ref No.: 250815). 	

	Name	Signature	Date
Recorded by	William Yeung	B	21 Aug 2025
Checked by	Karina Chan	Zalle	25 Aug 2025

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	250828
Date	28 August 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Remarks/Observations	Related Item No.
B. Water Quality	
No environmental deficiency was identified during site inspection.	
C. Air Quality	
No environmental deficiency was identified during site inspection.	
D. Construction Noise Impact	
E. Waste/Chemical Management	
No environmental deficiency was identified during site inspection.	
F. Visual and Landscape	
No environmental deficiency was identified during site inspection.	
• No environmental deficiency was identified during site inspection.	
H. Marine Ecology	
No environmental deficiency was identified during site inspection.	
I Othars	
	 B. Water Quality No environmental deficiency was identified during site inspection. C. Air Quality No environmental deficiency was identified during site inspection. D. Construction Noise Impact No environmental deficiency was identified during site inspection. E. Waste/Chemical Management No environmental deficiency was identified during site inspection. F. Visual and Landscape No environmental deficiency was identified during site inspection. G. Permits/Licences No environmental deficiency was identified during site inspection. H. Marine Ecology

	Name	Signature	Date
Recorded by	William Yeung	B	28 Aug 2025
Checked by	Karina Chan	Zalle	1 Sep 2025

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and **Associated Works**

Checklist Reference Number	250807
Date	07 August 2025 (Thursday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:250731), no major environmental deficiency	
	was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung	K	07 Aug 2025
Checked by	Karina Chan	Zalle	11 Aug 2025

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and **Associated Works**

Checklist Reference Number	250815
Date	15 August 2025 (Friday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:250807), no major environmental deficiency	
	was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung		15 Aug 2025
Checked by	Karina Chan	Zoll	18 Aug 2025

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and **Associated Works**

Checklist Reference Number	250821
Date	21 August 2025 (Thursday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	Follow up on the previous session (Ref No.:250815), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung		21 Aug 2025
Checked by	Karina Chan	Zoll	25 Aug 2025

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and **Associated Works**

Checklist Reference Number	250828
Date	28 August 2025 (Thursday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:250821), no major environmental deficiency	
	was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung	B	28 Aug 2025
Checked by	Karina Chan	Zelle	1 Sep 2025

Tseung Kwan O-Lam Tin Tunnel-Main Tunnel and Associated Works

Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	250806
Date	06 August 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. EcologyNo environmental deficiency was identified during site inspection.	
	D. Landscape & Visual	
	No environmental deficiency was identified during site inspection.	
	E. Air Quality	
	No environmental deficiency was identified during site inspection.	
	 F. Construction Noise Impact No environmental deficiency was identified during site inspection. 	
	G. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	H. Permits/ Licences	
	No environmental deficiency was identified during site inspection.	
	I. Impact on Cultural Heritage	
	No environmental deficiency was identified during site inspection.	
	J. Others	
	• Referring to the last site inspection report (Ref. no.: 250731), no major environmental deficiency was identified.	

	Name	Signature	Date
Recorded by	William Yeung		06 August 2025
Checked by	Karina Chan	Jeffer	07 August 2025

Tseung Kwan O-Lam Tin Tunnel-Main Tunnel and Associated Works

Checklist Reference Number	250813
Date	13 August 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

B. Water Quality	
D. Water Quality	
No environmental deficiency was identified during site inspection.	
C. Ecology	
No environmental deficiency was identified during site inspection.	
D. Landscape & Visual	
No environmental deficiency was identified during site inspection.	
E. Air Quality	
No environmental deficiency was identified during site inspection.	
F. Construction Noise Impact	
No environmental deficiency was identified during site inspection.	
G. Waste / Chemical Management	
No environmental deficiency was identified during site inspection.	
H. Permits/Licences	
No environmental deficiency was identified during site inspection.	
I. Impact on Cultural Heritage	
No environmental deficiency was identified during site inspection.	
J. Others	
	 C. Ecology No environmental deficiency was identified during site inspection. D. Landscape & Visual No environmental deficiency was identified during site inspection. E. Air Quality No environmental deficiency was identified during site inspection. F. Construction Noise Impact No environmental deficiency was identified during site inspection. G. Waste / Chemical Management No environmental deficiency was identified during site inspection. H. Permits/ Licences No environmental deficiency was identified during site inspection. I. Impact on Cultural Heritage No environmental deficiency was identified during site inspection.

	Name	Signature	Date
Recorded by	William Yeung		13 August 2025
Checked by	Karina Chan	Zoller	14 August 2025

Tseung Kwan O-Lam Tin Tunnel-Main Tunnel and Associated Works

Checklist Reference Number	250820
Date	20 August 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Ecology	
	No environmental deficiency was identified during site inspection.	
	D. Landscape & Visual	
	No environmental deficiency was identified during site inspection.	
	E. Air Quality	
	No environmental deficiency was identified during site inspection.	
	F. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	G. Waste / Chemical Management	
250820-R1	• The Contractor is reminded to remove the accumulated general refuse (i.e. water bottles) on the slope.	Gli
	H. Permits/ Licences	
	No environmental deficiency was identified during site inspection.	
	I. Impact on Cultural Heritage	
	No environmental deficiency was identified during site inspection.	
	J. Others	
	• Referring to the last site inspection report (Ref. no.: 250813), no major environmental deficiency was identified.	

	Name	Signature	Date
Recorded by	William Yeung	R	20 August 2025
Checked by	Karina Chan	Zelle	21 August 2025

Tseung Kwan O-Lam Tin Tunnel-Main Tunnel and Associated Works

Checklist Reference Number	250827
Date	27 August 2025 (Wednesday)
Time	09:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Ecology	
	No environmental deficiency was identified during site inspection.	
	D. Landscape & Visual	
	No environmental deficiency was identified during site inspection.	
	E. Air Quality	
	No environmental deficiency was identified during site inspection.	
	F. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	G. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	H. Permits/ Licences	
	No environmental deficiency was identified during site inspection.	
	I. Impact on Cultural Heritage	
	No environmental deficiency was identified during site inspection.	
	J. Others	
	• Follow up on previous audit session (Ref No.:250820), all recorded items had been rectified.	

	Name	Signature	Date
Recorded by	William Yeung	K	27 August 2025
Checked by	Karina Chan	Zelle	28 August 2025