Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

Appendix F - Site Audit Summary

February 2021

Items	Date	Status*	Follow up Action		
Water Quality					
Ecology					
Noise					
Landscape and Visual					
Air Quality					
Waste / Chemical Management					
Impact on Cultural Heritage					
Permits / Licenses					

- ✔ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit
- Solution/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit # Follow up action will be reported in next reporting month
- * Non-compliance of mitigation measure
- Non-compliance but improved by the contractor

MA20003/App F CINOTECH

Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

Appendix F - Site Audit Summary

March 2021

Items	Date	Status*	Follow up Action			
Water Quality						
Noise						
Landscape and Visual						
Air Quality						
Waste / Chemical Management						
The skip with accumulation of general refuse was observed	25 March 2021	~	Item was rectified on 16 April 2021			
Impact on Cultural Heritage						
Permits / Licenses						

[✓] Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit

• Non-compliance but rectified by the contractor

MA20003/App F CINOTECH

^{*} Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit

[#] Follow up action will be reported in next reporting month

^{*} Non-compliance of mitigation measure

Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

Appendix F - Site Audit Summary

April 2021

Items	Date	Status*	Follow up Action			
Water Quality						
Noise						
Landscape and Visual						
Air Quality						
Waste / Chemical Management	Waste / Chemical Management					
Accumulation of general refuse should be avoided.	01 April 2021	V	Item was rectified on 16 April 2021			
Accumulation of general refuse was observed continuously.	08 April 2021	~	Item was rectified on 16 April 2021			
Contractor shall avoid accumulation of general refuse.	16 April 2021	V	Item was rectified on 22 April 2021			
Accumulation of general refuse was observed	22 April 2021	V	Item was rectified on 29 April 2021			
Impact on Cultural Heritage						
Permits / Licenses						

- ✓ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit
- * Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit
- # Follow up action will be reported in next reporting month
- * Non-compliance of mitigation measure
- Non-compliance but rectified by the contractor

MA20003/App F CINOTECH