


Weekly Site Inspection Record Summary

Inspection Information

| | |
|----------------------------|----------------------------|
| Checklist Reference Number | 230202 |
| Date | 2 February 2023 (Thursday) |
| Time | 09:20 – 12:00 |

| Ref. No. | Non-Compliance | Related Item No. |
|----------|-----------------|------------------|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|------------|--|------------------|
| 230202- R2 | <p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none"> Spraying water s needed when breaking the concrete. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. | C15 |
| 230202- R1 | <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> Drip Tray should be provided for chemical container to prevent leakage. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> Follow up on the previous session (Ref No.:230126), all item has been rectified. | E9 |

| | Name | Signature | Date |
|-------------|-------------|--|-----------------|
| Recorded by | Alex NG |  | 2 February 2023 |
| Checked by | Karina Chan |  | 3 February 2023 |


Weekly Site Inspection Record Summary

Inspection Information

| | |
|----------------------------|----------------------------|
| Checklist Reference Number | 230209 |
| Date | 9 February 2023 (Thursday) |
| Time | 09:20 – 12:00 |

| Ref. No. | Non-Compliance | Related Item No. |
|----------|-----------------|------------------|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|------------|--|------------------|
| 230209- R1 | <p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> Drip Tray should be provided for chemical container to prevent leakage. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> Follow up on the previous session (Ref No.:230202), all item has been rectified. | E9 |

| | Name | Signature | Date |
|-------------|-------------|--|------------------|
| Recorded by | Alex NG |  | 9 February 2023 |
| Checked by | Karina Chan |  | 10 February 2023 |


Weekly Site Inspection Record Summary

Inspection Information

| | |
|----------------------------|-----------------------------|
| Checklist Reference Number | 230216 |
| Date | 16 February 2023 (Thursday) |
| Time | 09:20 – 12:00 |

| Ref. No. | Non-Compliance | Related Item No. |
|----------|-----------------|------------------|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|------------|--|------------------|
| 230216- R1 | <p>B. Water Quality</p> <ul style="list-style-type: none"> Stagnant water was observed in the west ventilation building. <p>C. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> Follow up on the previous session (Ref No.:230209), all item has been rectified. | B9 |

| | Name | Signature | Date |
|-------------|-------------|--|------------------|
| Recorded by | Alex NG |  | 16 February 2023 |
| Checked by | Karina Chan |  | 17 February 2023 |


Weekly Site Inspection Record Summary

Inspection Information

| | |
|----------------------------|-----------------------------|
| Checklist Reference Number | 230223 |
| Date | 23 February 2023 (Thursday) |
| Time | 09:20 – 12:00 |

| Ref. No. | Non-Compliance | Related Item No. |
|----------|-----------------|------------------|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|----------|---|------------------|
| | <p>B. Water Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>H. Marine Ecology</p> <ul style="list-style-type: none"> No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none"> Follow up on the previous session (Ref No.:230216), all item has been rectified. | |

| | Name | Signature | Date |
|-------------|-------------|--|------------------|
| Recorded by | Alex NG |  | 23 February 2023 |
| Checked by | Karina Chan |  | 24 February 2023 |

Contract No. ED/2020/03

Environmental Team for Trunk Road T2 – Traffic Control and Surveillance System (TCSS) and Associated Works

Site Inspection Record Summary

Inspection Information

| | |
|----------------------------|---------------------------|
| Checklist Reference Number | 230217 |
| Date | 17 February 2023 (Friday) |
| Time | 09:30 – 12:00 |

| Ref. No. | Non-Compliance | Related Item No. |
|----------|-----------------|------------------|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|----------|--|------------------|
| | <p>B. Water Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>C. Air Quality</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>D. Construction Noise Impact</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>E. Waste/Chemical Management</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>F. Visual and Landscape</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>G. Permits/Licences</p> <ul style="list-style-type: none">No environmental deficiency was identified during site inspection. <p>I. Others</p> <ul style="list-style-type: none">Follow up on the previous session (Ref No.:230113), no major environmental deficiency was identified during site inspection. | |

| | Name | Signature | Date |
|-------------|-------------|--|------------------|
| Recorded by | Alex Ng |  | 17 February 2023 |
| Checked by | Karina Chan |  | 18 February 2023 |