
**Weekly Site Inspection Record Summary**
**Inspection Information**

| | |
|---|---|
| Checklist Reference Number | 260903 |
| Date | 03 September 2026 (Thursday) |
| Time | 09:30 – 16:30 |

| Ref. No. | Non-Compliance | Related Item No. |
|---|---|---|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|---|---|---|
| 260903-EP451-R1 | ***B. Water Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***C. Air Quality***<br>• Water spaying should be provided to the breaking area.<br><br>***D. Construction Noise Impact***<br>• No environmental deficiency was identified during site inspection.<br><br>***E. Waste/Chemical Management***<br>• No environmental deficiency was identified during site inspection.<br><br>***F. Visual and Landscape***<br>• No environmental deficiency was identified during site inspection.<br><br>***G. Permits/Licences***<br>• No environmental deficiency was identified during site inspection.<br><br>***H. Marine Ecology***<br>• No environmental deficiency was identified during site inspection.<br><br>***I. Others***<br>• No environmental deficiency was identified in previous session (Ref No.: 260827) | *C15* |


| | Name | Signature | Date |
|---|---|---|---|
| Recorded by | William Yeung |  | 03 Sep 2026 |
| Checked by | Karina Chan |  | 07 Sep 2026 |

**Weekly Site Inspection Record Summary**
**Inspection Information**

| | |
|---|---|
| Checklist Reference Number | 260910 |
| Date | 10 September 2026 (Thursday) |
| Time | 09:30 – 16:30 |

| Ref. No. | Non-Compliance | Related Item No. |
|---|---|---|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|---|---|---|
| | ***B. Water Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***C. Air Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***D. Construction Noise Impact***<br>• No environmental deficiency was identified during site inspection.<br><br>***E. Waste/Chemical Management***<br>• No environmental deficiency was identified during site inspection.<br><br>***F. Visual and Landscape***<br>• No environmental deficiency was identified during site inspection.<br><br>***G. Permits/Licences***<br>• No environmental deficiency was identified during site inspection.<br><br>***H. Marine Ecology***<br>• No environmental deficiency was identified during site inspection.<br><br>***I. Others***<br>• Follow up on the previous session (Ref No.:260903), all the items have been rectified. | |


| | Name | Signature | Date |
|---|---|---|---|
| Recorded by | William Yeung |  | 10 Sep 2026 |
| Checked by | Karina Chan |  | 14 Sep 2026 |

**Weekly Site Inspection Record Summary**
**Inspection Information**

| | |
|---|---|
| Checklist Reference Number | 260917 |
| Date | 17 September 2026 (Thursday) |
| Time | 09:30 – 16:30 |

| Ref. No. | Non-Compliance | Related Item No. |
|---|---|---|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|---|---|---|
| 260917-EP451-R1 | ***B. Water Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***C. Air Quality***<br>• Stockpile of dusty material should be covered or water spraying should be provided.<br><br>***D. Construction Noise Impact***<br>• No environmental deficiency was identified during site inspection.<br><br>***E. Waste/Chemical Management***<br>• No environmental deficiency was identified during site inspection.<br><br>***F. Visual and Landscape***<br>• No environmental deficiency was identified during site inspection.<br><br>***G. Permits/Licences***<br>• No environmental deficiency was identified during site inspection.<br><br>***H. Marine Ecology***<br>• No environmental deficiency was identified during site inspection.<br><br>***I. Others***<br>• No environmental deficiency was identified in previous session (Ref No.: 260910). | *C09* |


| | Name | Signature | Date |
|---|---|---|---|
| Recorded by | William Yeung |  | 17 Sep 2026 |
| Checked by | Karina Chan |  | 21 Sep 2026 |

**Weekly Site Inspection Record Summary**
**Inspection Information**

| | |
|---|---|
| Checklist Reference Number | 260924 |
| Date | 24 September 2026 (Thursday) |
| Time | 09:30 – 16:30 |

| Ref. No. | Non-Compliance | Related Item No. |
|---|---|---|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|---|---|---|
| | ***B. Water Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***C. Air Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***D. Construction Noise Impact***<br>• No environmental deficiency was identified during site inspection.<br><br>***E. Waste/Chemical Management***<br>• No environmental deficiency was identified during site inspection.<br><br>***F. Visual and Landscape***<br>• No environmental deficiency was identified during site inspection.<br><br>***G. Permits/Licences***<br>• No environmental deficiency was identified during site inspection.<br><br>***H. Marine Ecology***<br>• No environmental deficiency was identified during site inspection.<br><br>***I. Others***<br>• Follow up on the previous session (Ref No.:260917), all the items have been rectified. | |


| | Name | Signature | Date |
|---|---|---|---|
| Recorded by | William Yeung |  | 24 Sep 2026 |
| Checked by | Karina Chan |  | 28 Sep 2026 |

**Weekly Site Inspection Record Summary**
**Inspection Information**

| | |
|---|---|
| Checklist Reference Number | 260930 |
| Date | 30 September 2026 (Wednesday) |
| Time | 09:30 – 16:30 |

| Ref. No. | Non-Compliance | Related Item No. |
|---|---|---|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|---|---|---|
| | ***B. Water Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***C. Air Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***D. Construction Noise Impact***<br>• No environmental deficiency was identified during site inspection.<br><br>***E. Waste/Chemical Management***<br>• No environmental deficiency was identified during site inspection.<br><br>***F. Visual and Landscape***<br>• No environmental deficiency was identified during site inspection.<br><br>***G. Permits/Licences***<br>• No environmental deficiency was identified during site inspection.<br><br>***H. Marine Ecology***<br>• No environmental deficiency was identified during site inspection.<br><br>***I. Others***<br>• No environmental deficiency was identified in previous session (Ref No.: 260924). | |

| | Name | Signature | Date |
|---|---|---|---|
| Recorded by | William Yeung |  | 30 Sep 2026 |
| Checked by | Karina Chan |  | 02 Oct 2026 |


## Site Inspection Record Summary

**Inspection Information**

| | |
|---|---|
| Checklist Reference Number | 260903 |
| Date | 03 September 2026 (Thursday) |
| Time | 09:30 – 12:30 |

| Ref. No. | Non-Compliance | Related Item No. |
|---|---|---|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|---|---|---|
| | ***B. Water Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***C. Air Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***D. Construction Noise Impact***<br>• No environmental deficiency was identified during site inspection.<br><br>***E. Waste/Chemical Management***<br>• No environmental deficiency was identified during site inspection.<br><br>***F. Visual and Landscape***<br>• No environmental deficiency was identified during site inspection.<br><br>***G. Permits/Licences***<br>• No environmental deficiency was identified during site inspection.<br><br>***I. Others***<br>• Follow up on the previous session (Ref No.:260827), no major environmental deficiency was identified during site inspection. | |

| | Name | Signature | Date |
|---|---|---|---|
| Recorded by | William Yeung |  | 03 Sep 2026 |
| Checked by | Karina Chan |  | 07 Sep 2026 |


## Site Inspection Record Summary

**Inspection Information**

| | |
|---|---|
| Checklist Reference Number | 260911 |
| Date | 11 September 2026 (Friday) |
| Time | 09:30 – 12:30 |

| Ref. No. | Non-Compliance | Related Item No. |
|---|---|---|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|---|---|---|
| | ***B. Water Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***C. Air Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***D. Construction Noise Impact***<br>• No environmental deficiency was identified during site inspection.<br><br>***E. Waste/Chemical Management***<br>• No environmental deficiency was identified during site inspection.<br><br>***F. Visual and Landscape***<br>• No environmental deficiency was identified during site inspection.<br><br>***G. Permits/Licences***<br>• No environmental deficiency was identified during site inspection.<br><br>***I. Others***<br>• Follow up on the previous session (Ref No.:260903), no major environmental deficiency was identified during site inspection. | |

| | Name | Signature | Date |
|---|---|---|---|
| Recorded by | William Yeung |  | 11 Sep 2026 |
| Checked by | Karina Chan |  | 15 Sep 2026 |


## Site Inspection Record Summary

**Inspection Information**

| | |
|---|---|
| Checklist Reference Number | 260917 |
| Date | 17 September 2026 (Thursday) |
| Time | 09:30 – 12:30 |

| Ref. No. | Non-Compliance | Related Item No. |
|---|---|---|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|---|---|---|
| | ***B. Water Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***C. Air Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***D. Construction Noise Impact***<br>• No environmental deficiency was identified during site inspection.<br><br>***E. Waste/Chemical Management***<br>• No environmental deficiency was identified during site inspection.<br><br>***F. Visual and Landscape***<br>• No environmental deficiency was identified during site inspection.<br><br>***G. Permits/Licences***<br>• No environmental deficiency was identified during site inspection.<br><br>***I. Others***<br>• Follow up on the previous session (Ref No.:260911), no major environmental deficiency was identified during site inspection. | |

| | Name | Signature | Date |
|---|---|---|---|
| Recorded by | William Yeung |  | 17 Sep 2026 |
| Checked by | Karina Chan |  | 21 Sep 2026 |


## Site Inspection Record Summary

**Inspection Information**

| | |
|---|---|
| Checklist Reference Number | 260924 |
| Date | 24 September 2026 (Thursday) |
| Time | 09:30 – 12:30 |

| Ref. No. | Non-Compliance | Related Item No. |
|---|---|---|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|---|---|---|
| | ***B. Water Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***C. Air Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***D. Construction Noise Impact***<br>• No environmental deficiency was identified during site inspection.<br><br>***E. Waste/Chemical Management***<br>• No environmental deficiency was identified during site inspection.<br><br>***F. Visual and Landscape***<br>• No environmental deficiency was identified during site inspection.<br><br>***G. Permits/Licences***<br>• No environmental deficiency was identified during site inspection.<br><br>***I. Others***<br>• Follow up on the previous session (Ref No.:260917), no major environmental deficiency was identified during site inspection. | |

| | Name | Signature | Date |
|---|---|---|---|
| Recorded by | William Yeung |  | 24 Sep 2026 |
| Checked by | Karina Chan |  | 28 Sep 2026 |


## Site Inspection Record Summary

**Inspection Information**

| | |
|---|---|
| Checklist Reference Number | 260930 |
| Date | 30 September 2026 (Wednesday) |
| Time | 09:30 – 12:30 |

| Ref. No. | Non-Compliance | Related Item No. |
|---|---|---|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|---|---|---|
| | ***B. Water Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***C. Air Quality***<br>• No environmental deficiency was identified during site inspection.<br><br>***D. Construction Noise Impact***<br>• No environmental deficiency was identified during site inspection.<br><br>***E. Waste/Chemical Management***<br>• No environmental deficiency was identified during site inspection.<br><br>***F. Visual and Landscape***<br>• No environmental deficiency was identified during site inspection.<br><br>***G. Permits/Licences***<br>• No environmental deficiency was identified during site inspection.<br><br>***I. Others***<br>• Follow up on the previous session (Ref No.:260924), no major environmental deficiency was identified during site inspection. | |

| | Name | Signature | Date |
|---|---|---|---|
| Recorded by | William Yeung |  | 30 Sep 2026 |
| Checked by | Karina Chan |  | 02 Oct 2026 |