
Weekly Site Inspection Record Summary
Inspection Information

Checklist Reference Number	260903
Date	03 September 2026 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality • No environmental deficiency was identified during site inspection. ***C. Air Quality*** • No environmental deficiency was identified during site inspection. ***D. Construction Noise Impact*** • No environmental deficiency was identified during site inspection. ***E. Waste/Chemical Management*** • No environmental deficiency was identified during site inspection. ***F. Visual and Landscape*** • No environmental deficiency was identified during site inspection. ***G. Permits/Licences*** • No environmental deficiency was identified during site inspection. ***H. Marine Ecology*** • No environmental deficiency was identified during site inspection. ***I. Others*** • No environmental deficiency was identified in previous session (Ref No.: 260827).	


	Name	Signature	Date
Recorded by	William Yeung		03 Sep 2026
Checked by	Karina Chan		07 Sep 2026

Weekly Site Inspection Record Summary
Inspection Information

Checklist Reference Number	260910
Date	10 September 2026 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality • No environmental deficiency was identified during site inspection. ***C. Air Quality*** • No environmental deficiency was identified during site inspection. ***D. Construction Noise Impact*** • No environmental deficiency was identified during site inspection. ***E. Waste/Chemical Management*** • No environmental deficiency was identified during site inspection. ***F. Visual and Landscape*** • No environmental deficiency was identified during site inspection. ***G. Permits/Licences*** • No environmental deficiency was identified during site inspection. ***H. Marine Ecology*** • No environmental deficiency was identified during site inspection. ***I. Others*** • No environmental deficiency was identified in previous session (Ref No.: 260903).	


	Name	Signature	Date
Recorded by	William Yeung		10 Sep 2026
Checked by	Karina Chan		14 Sep 2026

Weekly Site Inspection Record Summary
Inspection Information

Checklist Reference Number	260917
Date	17 September 2026 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality • No environmental deficiency was identified during site inspection. ***C. Air Quality*** • No environmental deficiency was identified during site inspection. ***D. Construction Noise Impact*** • No environmental deficiency was identified during site inspection. ***E. Waste/Chemical Management*** • No environmental deficiency was identified during site inspection. ***F. Visual and Landscape*** • No environmental deficiency was identified during site inspection. ***G. Permits/Licences*** • No environmental deficiency was identified during site inspection. ***H. Marine Ecology*** • No environmental deficiency was identified during site inspection. ***I. Others*** • No environmental deficiency was identified in previous session (Ref No.: 260910).	


	Name	Signature	Date
Recorded by	William Yeung		17 Sep 2026
Checked by	Karina Chan		21 Sep 2026

Weekly Site Inspection Record Summary
Inspection Information

Checklist Reference Number	260924
Date	24 September 2026 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
260924-EP458-R1	***B. Water Quality*** • Ponding water was observed at the Portion Q2. ***C. Air Quality*** • No environmental deficiency was identified during site inspection. ***D. Construction Noise Impact*** • No environmental deficiency was identified during site inspection.	B09
260924-EP458-R2	***E. Waste/Chemical Management*** • General refuse should be removed to improve housekeeping at Portion Q1. ***F. Visual and Landscape*** • No environmental deficiency was identified during site inspection. ***G. Permits/Licences*** • No environmental deficiency was identified during site inspection. ***H. Marine Ecology*** • No environmental deficiency was identified during site inspection. ***I. Others*** • No environmental deficiency was identified in previous session (Ref No.: 260917).	E01iii


	Name	Signature	Date
Recorded by	William Yeung		24 Sep 2026
Checked by	Karina Chan		28 Sep 2026

Weekly Site Inspection Record Summary
Inspection Information

Checklist Reference Number	260930
Date	30 September 2026 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
260930-EP458-R1	***B. Water Quality*** • No environmental deficiency was identified during site inspection. ***C. Air Quality*** • Stockpile of dusty material should be covered or water spraying should be provided. ***D. Construction Noise Impact*** • No environmental deficiency was identified during site inspection. ***E. Waste/Chemical Management*** • No environmental deficiency was identified during site inspection. ***F. Visual and Landscape*** • No environmental deficiency was identified during site inspection. ***G. Permits/Licences*** • No environmental deficiency was identified during site inspection. ***H. Marine Ecology*** • No environmental deficiency was identified during site inspection. ***I. Others*** • Follow up on the previous session (Ref No.:260924), all the items have been rectified.	*C09*


	Name	Signature	Date
Recorded by	William Yeung		30 Sep 2026
Checked by	Karina Chan		02 Oct 2026

Site Inspection Record Summary
Inspection Information

Checklist Reference Number	260903
Date	03 September 2026 (Thursday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality • No environmental deficiency was identified during site inspection. ***C. Air Quality*** • No environmental deficiency was identified during site inspection. ***D. Construction Noise Impact*** • No environmental deficiency was identified during site inspection. ***E. Waste/Chemical Management*** • No environmental deficiency was identified during site inspection. ***F. Visual and Landscape*** • No environmental deficiency was identified during site inspection. ***G. Permits/Licences*** • No environmental deficiency was identified during site inspection. ***I. Others*** • Follow up on the previous session (Ref No.:260827), no major environmental deficiency was identified during site inspection.	


	Name	Signature	Date
Recorded by	William Yeung		03 Sep 2026
Checked by	Karina Chan		07 Sep 2026

Site Inspection Record Summary
Inspection Information

Checklist Reference Number	260911
Date	11 September 2026 (Friday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality • No environmental deficiency was identified during site inspection. ***C. Air Quality*** • No environmental deficiency was identified during site inspection. ***D. Construction Noise Impact*** • No environmental deficiency was identified during site inspection. ***E. Waste/Chemical Management*** • No environmental deficiency was identified during site inspection. ***F. Visual and Landscape*** • No environmental deficiency was identified during site inspection. ***G. Permits/Licences*** • No environmental deficiency was identified during site inspection. ***I. Others*** • Follow up on the previous session (Ref No.:260903), no major environmental deficiency was identified during site inspection.	


	Name	Signature	Date
Recorded by	William Yeung		11 Sep 2026
Checked by	Karina Chan		15 Sep 2026

Site Inspection Record Summary
Inspection Information

Checklist Reference Number	260917
Date	17 September 2026 (Thursday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality • No environmental deficiency was identified during site inspection. ***C. Air Quality*** • No environmental deficiency was identified during site inspection. ***D. Construction Noise Impact*** • No environmental deficiency was identified during site inspection. ***E. Waste/Chemical Management*** • No environmental deficiency was identified during site inspection. ***F. Visual and Landscape*** • No environmental deficiency was identified during site inspection. ***G. Permits/Licences*** • No environmental deficiency was identified during site inspection. ***I. Others*** • Follow up on the previous session (Ref No.:260911), no major environmental deficiency was identified during site inspection.	


	Name	Signature	Date
Recorded by	William Yeung		17 Sep 2026
Checked by	Karina Chan		21 Sep 2026

Site Inspection Record Summary
Inspection Information

Checklist Reference Number	260924
Date	24 September 2026 (Thursday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality • No environmental deficiency was identified during site inspection. ***C. Air Quality*** • No environmental deficiency was identified during site inspection. ***D. Construction Noise Impact*** • No environmental deficiency was identified during site inspection. ***E. Waste/Chemical Management*** • No environmental deficiency was identified during site inspection. ***F. Visual and Landscape*** • No environmental deficiency was identified during site inspection. ***G. Permits/Licences*** • No environmental deficiency was identified during site inspection. ***I. Others*** • Follow up on the previous session (Ref No.:260917), no major environmental deficiency was identified during site inspection.	


	Name	Signature	Date
Recorded by	William Yeung		24 Sep 2026
Checked by	Karina Chan		28 Sep 2026

Site Inspection Record Summary
Inspection Information

Checklist Reference Number	260930
Date	30 September 2026 (Wednesday)
Time	09:30 – 12:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality • No environmental deficiency was identified during site inspection. ***C. Air Quality*** • No environmental deficiency was identified during site inspection. ***D. Construction Noise Impact*** • No environmental deficiency was identified during site inspection. ***E. Waste/Chemical Management*** • No environmental deficiency was identified during site inspection. ***F. Visual and Landscape*** • No environmental deficiency was identified during site inspection. ***G. Permits/Licences*** • No environmental deficiency was identified during site inspection. ***I. Others*** • Follow up on the previous session (Ref No.:260924), no major environmental deficiency was identified during site inspection.	

	Name	Signature	Date
Recorded by	William Yeung		30 Sep 2026
Checked by	Karina Chan		02 Oct 2026